

## Town of Acton Department of Public Health

472 Main Street Acton, MA 01720

Telephone: (978) 929-6632

Fax: (978) 929-6340

April 15, 2015

Gordon Richards 21 Maple Street Acton, MA 01720

Mr. Richards,

Today the Acton Health Department conducted a Hazardous Materials Inspection at your property, 21 Maple Street. We knocked at your door with no response, but as you said on the phone, you said to proceed with the inspection regardless of your presence. The inspection report is enclosed with this letter. The only thing we could not find was extra speedy dry, cat litter or equivalent, which should be available in case of any spills, especially outside the bermed area. Please provide these clean up materials in a convenient location to the hazardous materials.

If you have any questions, please feel free to contact me Monday-Friday between 8AM-5PM.

Best Regards,

Evan Carloni, REHS/RS



## Town of Acton Department of Public Health

472 Main Street, Acton, MA 01720 Phone: (978) 929-6632 Fax: (978) 929-6340 www.acton-ma.gov

## ANNUAL INSPECTION HAZARDOUS MATERIALS PERMIT HOLDER

Facility Name:	Gordon Richards			Date 4/15/15	
Address: 21 Maple Street					
Type of Business: Foundation company					
Telephone: 978-263-9195			Email:		
Contact Person:				Initial Inspection Re-Inspection	
Housekeeping:		Y	N	Comments	
Area clean		<b>V</b>			
Spills present			<b>V</b>		
Appropriate material storage		1			
Materials and wastes separate		<b>V</b>			
Cleanup materials available			×	Please provide speedy dry or equivalent in	
Materials have secondary containment		1		case of spill	
Materials and wastes are labeled		1			
Safety:					
Are MSDS sheets available on site		1			
Employee personal protective equipment on site		1			
Employees trained in Haz Mat handling		1			
Emergency procedures posted		1		100	
Site Management:					
Waste removed by licensed hauler			<b>V</b>	No waste	
Floor drains present in area of Haz Mat or waste			<b>/</b> _	1065	
Sinks present in area of Haz Mat or waste			<b>V</b>		
Testing of septic system necessary			<b>V</b>		
Does site plan on file reflect current arrangement		1			
Any UST (underground storage tank) present			✓.		
If UST present, is it alarmed			<b>V</b>		
Action Items:  1. Speedy dry observed spread in containment area but could not find container in case of 2. spills outside of containment. Please provide.  3. Re-inspection required? Yes \(\sigma\) No \(\sigma\)			4 5 6 Re	e-inspection Date:	
Inspector Signature Date			F2	acility Representative Signature Date	
inspector dignature Date			I worked traditional and interest and in the second		

D. H/17/18